

Priority Colonias of Nueces County During November 2002 Flooding


This map was generated by the Center for Water Supply Studies using GIS (Geographical Information Systems) software. No claims are made to the accuracy or completeness of the information shown herein nor to its suitability for a particular use. The scale and location of all mapped data are approximate. Some data are preliminary.

Legend

- Priority Colonias
- Rural Subdivisions Listed in Comprehensive Survey
- County Line

LandSat TM 7+ Bands 742 06-NOV-2002

- Red: Band_1
- Green: Band_2
- Blue: Band_3



Name: Cindy Park
Location:
Coordinates: 14R0612740; UTM 3083661
Remarks: Substandard housing. Appears to be of poor economic status. We entered it from the Ranch. Comprehensive Survey carries both the Ranch and Cindy Park as one colonia.

Name: Country Estates, West
Location:
Coordinates: 14R0610180; UTM 3085200
Remarks: Subdivision seems to cover large area. There is a mix of houses and mobile homes. Most appear to have water wells, one resident hauls water in. Economic status is undeterminable.

Name: Western Ridge
Location:
Coordinates: 14R0610176; UTM 3084931
Remarks: Variety of housing, including mobile homes; appears to be of low to middle income economic status.

Name: Banquete town site
Location: Highway 44
Coordinates: 14R0618040 / UTM 3076075
Remarks: Houses and mobile homes in poor condition. Home to many elderly on fixed incomes.

Name: Ja-Lin
Location: Edge of Banquete, Texas
Coordinates: 14R0618856 / UTM 3075954
Remarks: Appears to be very poor; abandoned houses; trash and debris prevalent.

Name: Primavera
Location:
Coordinates: pending
Remarks: Trash and debris prevalent; many abandoned vehicles; unkempt ditches. Some water wells, but many homes without. Home-made septic systems; roads in very poor condition. Appears to be of poor economic status.

Name: Nye Peterson Subdivision
Location: CR 30 near Nye Peterson Road
Coordinates: Pending
Remarks: Houses and trailers in poor condition. Appears to be of poor economic status. Frequent flooding.

Name: Lost Creek
Location: CR 28 & CR 81
Coordinates: Pending
Remarks: Frequent flooding. Trash and debris prevalent. Appears to be of poor economic status.

Name: Santa Petronilla Estates # 5
Location: CR 67 B & CR 24
Coordinates: Pending
Remarks: Old housing, mostly trailers. Substandard new housing, appears to be of mixed poor and middle-class economic status.

Name: Casa Court # 1
Location: Casa Court # 1
Coordinates: 14R0617422 / UTM3052665
Remarks: Dilapidated homes; overall in bad condition. Appears to be of poor economic status. Private company trash pick up. Small in size.

Name: Bluntzer Place
Location:
Coordinates: 14R0619160; UTM 3086377
Remarks: Homes of various conditions and values. Well water prevalent. Trash and abandoned autos. Appears to be of poor to moderate economic status; no public services apparent.

Name: Las Milpas
Location:
Coordinates: 14R0619457; UTM 3086272
Remarks: Appears to be of predominantly poor economic status with some homes of middle-class status.

Name: Quail Hill Unit 1, 2, 3 & 4
Location: CR 40 & CR 87 A. Near Banquete town site
Coordinates: 14R0619607 / UTM 3876014
Remarks: Trash, debris and old tires prevalent; abandoned autos. Appears to be of very poor economic status.

Name: Nueces Farm Tracts
Location:
Coordinates: 14R0623049; UTM 3077098
Remarks: Few homes, perhaps five total; economic status unknown.

Name: Bluebonnet Subdivision, Additions 1 & 2
Location: Edge of city limits of Robstown
Coordinates: 14R0629706 / UTM 3076285
Remarks: Trash and debris prevalent; water, gas and sanitation available. Appears to be of poor economic status.

Name: Primavera Estates
Location:
Coordinates: pending
Remarks: Frequent flooding. Appears to be of poor economic status.

Name: Spring Gardens #s 1, 2, 3
Location: CR 36 between CR 79 & 81
Coordinates: Pending
Remarks: Frequent flooding. Appears to be of poor economic status.

Name: Primavera
Location:
Coordinates: pending
Remarks: Frequent flooding. Appears to be of poor economic status.

Name: Primavera
Location:
Coordinates: pending
Remarks: Frequent flooding. Appears to be of poor economic status.

Name: Primavera
Location:
Coordinates: pending
Remarks: Frequent flooding. Appears to be of poor economic status.

Name: Primavera
Location:
Coordinates: pending
Remarks: Frequent flooding. Appears to be of poor economic status.

Name: Primavera
Location:
Coordinates: pending
Remarks: Frequent flooding. Appears to be of poor economic status.

Name: San Pedro
Location: Intersection of Ave. B & Bosquez, Robstown area
Coordinates: 14R0629889; UTM 3074988
Remarks: Water, gas and sewer available. Appears to be of low economic status. Outside of Robstown city limits.

Name: Rose Acres
Location: Corpus Christi ETJ
Coordinates: 14R0647513 / UTM3068754
Remarks: Predominantly elderly population. Appears to be of poor economic status. Flooding. Some substandard housing. In process of being platted, grant for water in progress.

Name: Tierra Verde # 1, 2, 3
Location:
Coordinates: Pending
Remarks: Homes and mobile homes of varying quality, mostly poor. Abandoned autos; apparently used as junkyard. Appears to be of poor economic status.

Name: Tierra Grande
Location: FM 665 and CR 61
Coordinates: Pending
Remarks: Unpaved roads; frequent flooding; poor drainage. Water available but cost-prohibitive. Septic systems inadequate during floods. Appears to be of poor economic status.

Name: Petronilla Acres Unit 1
Location:
Coordinates: Pending
Remarks: Abandoned autos prevalent. Water not available for some homes; well water is not drinkable. Frequent flooding. Economic status undetermined.

Name: San Petronilla Est. No. 1 & 2
Location: (14F?) at CR 63
Coordinates: Pending
Remarks: Poor to moderate housing. Frequent flooding. Abandoned autos. Water available to some; well water is not drinkable. Appears to be of poor to moderate economic status.

Name: San Petronilla Est. No. 5
Location: CR 75 off of FM 665
Coordinates: pending
Remarks: Abandoned mobile homes and oilfield equipment. Appears to be of poor economic status. Apparently has running water; unkempt ditches; septic tanks.

Name: San Petronilla Est. No. 5
Location: CR 75 off of FM 665
Coordinates: pending
Remarks: Abandoned mobile homes and oilfield equipment. Appears to be of poor economic status. Apparently has running water; unkempt ditches; septic tanks.

Name: San Petronilla Est. No. 5
Location: CR 75 off of FM 665
Coordinates: pending
Remarks: Abandoned mobile homes and oilfield equipment. Appears to be of poor economic status. Apparently has running water; unkempt ditches; septic tanks.

Name: San Petronilla Est. No. 5
Location: CR 75 off of FM 665
Coordinates: pending
Remarks: Abandoned mobile homes and oilfield equipment. Appears to be of poor economic status. Apparently has running water; unkempt ditches; septic tanks.

Name: San Petronilla Est. No. 5
Location: CR 75 off of FM 665
Coordinates: pending
Remarks: Abandoned mobile homes and oilfield equipment. Appears to be of poor economic status. Apparently has running water; unkempt ditches; septic tanks.

Name: San Petronilla Est. No. 5
Location: CR 75 off of FM 665
Coordinates: pending
Remarks: Abandoned mobile homes and oilfield equipment. Appears to be of poor economic status. Apparently has running water; unkempt ditches; septic tanks.